

## Uni-T UT395 & 396 Laser Distance Meter

50m~120m Range Finder with 2MP Lens Rangefinder  
Best Accuracy 2mm      USB Data Export PC Software




### Function Keys






**UT396 series**



**UT395 series**



## Measure and Base Chose



V

● Short Press the key  to chose Measure Base

● Short Press the key  under the measuring model and laser will start



## Continuous Measure to Find Max/Min Distance



User can use this function to find the target distance without frequent operation. The MAX and the MIN value will be shown on the screen.



## Area and Volume Measure




Press the key of  to choose Area or Valume measure and then measure the High Lengh (or Wide), the digital meter will automatically calcelate the Area or Valune.






## Triangle Pythagorean

1




To measure Length **c** and Angle **a**  
get the Length **a** and **b**


Applies to




2



To measure Length **c** and **a**  
get the Length **b**




3




To measure Length **b** and **a**  
get the Length **c**




4





To measure Length **a** **b** and **h**  
get the Length **c**




5



To measure Length **a** **b** and **I**  
get the Length **c**



**6**

To measure Length **a** **b** and **c**  
get the triangle area **S**




\*\*Attention please **1** ~ **6** modes are calculated automatically  
you just need to measure a, b or c.




## Staking-out Measure

User can use staking-out function to find the position which match the setting distance



## Multi-directional Electronic Leveler and Angle Measure






Instead of normal level meter to be more accuracy




## 2MP Lens Auxiliary Measurement (ONLY 396A 396B)



laser point area but can't be watch by eye  
because of far and sunlight

User can measure the distance through auxiliary  
measurement. The camera pixel 2 million.

\*\*Notice: UT395A UT395B UT395C without this function. this lens is only for UT396A UT396B.



laser point




## Photos






## USB Data Export



- When you received it, you can contact with us or go to our official websit to download 395,396 series laser distance meter PC software.
- The device is offered with open USB HID for users to do further development.





## Optical Lens Two Photographic



## Color Display With Own Operating System



package





## Learn More Model

	Standard						Professional											
Model	UT390B+	UT391+	UT392A	UT392B	UT393A	UT393B	UT395A	UT395B	UT395C	UT396A	UT396B							
Range	40m	60m	80m	100m	120m	150m	50m	70m	100m	80m	120m							
Min Unit							1mm											
Accuracy**							± ( 1.5mm+d*5/100000 )											
Max Laser Power							<1mW											
Laser Wave Length	620nm~680nm						635nm											
Features																		
Max/Min/Continuous	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓							
Area/ Volume	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓							
Triangle Pythagorean	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓							
Triangle Height/ Angle	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓							
Triangle Area	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓							
Storage Quantity	30 pcs				100 pcs													
Delay Measurement	X	X	X	X	✓	✓	✓	✓	✓	✓	✓							
Staking-out	X	X	X	X	✓	✓	✓	✓	✓	✓	✓							
Extended End Base	X	X	X	X	✓	✓	✓	✓	✓	✓	✓							
Dip Angle Range	X	X	X	X	X	X	-90.0°~90.0°											
Universal Electron Level Ruler	X	X	X	X	X	X	✓	✓	✓	✓	✓							
USB Connector	X	X	X	X	X	X	✓	✓	✓	✓	✓							
Camera	X	X	X	X	X	X	X	X	X	2MP Lens								
Auto Power off	✓	✓	✓	✓	✓	✓	100s-300s (adjustable)											
Auto Laser off	✓	✓	✓	✓	✓	✓	20s-120s( adjustable )											
Storage Temperature	-20°C~60°C																	
Operating Temperature	0°C~40°C																	
Storage Humidity	RH85%																	
General Characteristics																		
Dimension	112mm*50mm*25mm						126*56*28mm											
Battery	1.5V Alkaline Batteries (7#) *2						1.2V 800mAh AAANI-MH battery *3											
Package	Gift Box, User Manual, Warranty Card, Bags						Gift Box, User Manual, Warranty Card, Hang Rope, USB Cable, Bags, Rechargeable Battery (include)											



















